



SOUTH CENTRAL RAILWAY

Office of the Principal Chief Commercial Manager

1st Floor, Rail Nilayam, Secunderabad – 500 025. FAX: 88486(Rly.) & 040-23446826 (BSNL)

No. C/CR/UTS/Mobile Ticketing/2019

Dt. 08/11/2022

Sr.DCMs,/SC, HYB, BZA, GTL, GNT & NED

Sub: Station specific QR codes for obtaining unreserved tickets through “UTS” mobile app – Displaying at all Stations in the booking area – Reg.

Ref: GM/SCR’s Inspection notes, dt. 05/11/2022 (copy enclosed).

A copy of the reference cited is enclosed herewith. During the inspection of GM on NED Division on 25/9/2022, it was noticed that QR codes for obtaining tickets through “UTS” mobile app were not available at some of the Stations. It is reiterated that station specific QR codes through which a passenger, who is also in the station premises can obtain tickets through “UTS” mobile app should be displayed conspicuously at various places in the booking area at all Stations without fail.

These station specific QR codes have already been shared with the Divisions earlier and are also made available in the relevant folders in the CCM server. In case of any clarifications/requirement, Stations concerned may contact the Console/UTS database at Headquarters. Compliance on the above may be advised by 15/11/2022 so as to furnish reply to Para No. 4.02 of the GM’s inspection note referred above.

Encl: As above

के. राश. राव 8/11/2022
CCM/PM/SC

Copy submitted to: PCCM for information pls.

79005

G.M.F. 2022
31/11/22

Actionable Items noted during the Inspection of Shri Arun Kumar Jain, GM (In-charge) in Nanded division, on 25.09.2022.

Accompanied by DRM/NED, CPM/GS/NED, Branch Officers of Nanded division and Dy.CSTE/Projects.

CCM/PS
CCM/PM

Action on 4.01 & 4.02

eg

Sl. No.	Description	Action By
1	DRM/NED mentioned that ROB at AWB yard @ km 112/7-8 was constructed on cost sharing basis and commissioned but LC is not closed. There is demand from local people for one RUB for light vehicle traffic. The feasibility may be studied and necessary LHS subway may be proposed duly coordinating with DC/AWB, on cost sharing basis.	PCE DRM/NED
2	<p>Rear Window Inspection by Train No: 17663, between AWB – NSL section: The following deficiencies were observed during the rear window inspection -</p> <ul style="list-style-type: none"> Ballast deficiency observed at following Kms: <ul style="list-style-type: none"> KM 108/0-110/0 KM 98/0 – 99/0 Released sleepers in Daulatabad yard need to be removed. Weeds on platforms at Daulatabad, Lasur and Karanjgaon must be removed. Daulatabad over shoot line needs attention. Road surface at LC 45 needs attention. Misalignment at the following Kms need to be attended: <ul style="list-style-type: none"> Km 97/1 – 96/8 Km 96/2-3 Km 91/8 Km 28/0 – 1 Km 27/5 – 6 Cross level at Km 94/6 – 93/8 needs to be attended. Rough running on P.No: 32 at POZ yard. Check rail removed at LC No: 28, removed in view of ongoing TRR work, need to be refixed immediately. Bridge approach alignment at Km 60/9 needs to be attended. Trolley refuse at Km 58/9 – 59/2 to be set right. Alignment on Point No: 13 B at RGO yard at Km 52/0 needs attention. TR up goods warning board to be provided with retro reflective painting. LC No: 12 up goods warning board to be provided with retro reflective painting. Up distant warning board of NSL station is slightly bent. It needs to be rectified. 	PCE DRM/NED
3	It was informed that local people are not allowing to construct RUB at LC No: 20 at Km 48/0 – 1. Intervention and Assistance of District Authorities need to be taken for execution of the work.	DRM/NED
4	Nagarsol	
4.01	Billing machine of Milk stall need to be kept in working order. Sales register for daily sales at the stall must be maintained.	PCCM DRM/NED

4.02	QR code for UTS ticketing through UTS ON MOBILE APP is not available. This must be made available, immediately at all booking counters of all divisions.	PCCM DRM/NED
4.03	Debris and Weeds in circulating area need to be removed immediately.	DRM/NED
4.04	Station building brightening need to be done.	
4.05	Land acquisition for additional Loop line need to be expedited.	PCE DRM/NED
4.06	Division has identified vacant Dormitory Room on the first floor of the building to be used as Relay Room. Modification need to be carried out immediately so that Relay Room work can be started at the earliest.	PCSTE DRM/NED
4.07	The works of Relay Room need to be completed by December, so that NI can be planned at the earliest by getting T 28 Machine at the earliest.	
4.08	The progress of proposed new building under construction is very slow. This work need to be expedited and it may be converted as Dormitory later.	PCE DRM/NED
4.09	The estimate need to be reviewed thoroughly and revised estimate must be processed immediately. Possibility of proposing separate work for proposed additional Loop lines for Electrification need to be explored.	PCEE DRM/NED CPD/RE

South Central Railway

General Manager's Office
Secunderabad

No:G/120/Insp/NED/2022

05.11.2022

Forwarded to:

AGM for kind information.

PCE, PCCM, PCSTE, PCEE, DRM/NED & CPD/RE for compliance.

Sreenivas Reddy
(N. Sreenivas Reddy)
DGM/Co & Secretary to GM