

**Minute to Minute program of GM's Annual Inspection on 16.02.2021 (Tuesday)**

**GDR-TEL Section**

S. No.	km	Station/ Block Section	Arr (HH:MM)	Dep (HH:MM)	Duration of halt in Minutes	Assets Offered	Remarks
1	136.04	GDR	--	08:30			
2	147/4-6	MBL-KMLP	08:45	08:55	10	Inspection of Bridge No.287A (RUB), Span 1x4.50m	
	151.60	KMLP	09.00	09.15	15	--	P/ 02643 (ERS-PNBE)
3	155/12-14	KMLP-VKT	09.20	09.30	10	Inspection of LC No.106, Class-SPL, TVUs-65440.2, Census-02.06.2018, Interlocked	
4	155/22-156/4	KMLP-VKT	09:35	09:45	10	Inspection of Curve no.11 DN line (1 Degree)	
5	156/12-14	KMLP-VKT	09:50	10.00	10	Inspection of Minor Bridge No.302DN, Span 1x3.05 m	
6	157.85	VKT	10.05	10.20	15	Inspection of Venkatachalam station.	
7	157/0-172/0	VKT-NLR	10.20	10.30		Speed test 120 Kmph for 15 kms	
8	206/6-8	AXR-BTTR	10:55	11.05	10	Inspection of Minor Bridge No.443DN, Span 2x5.00 m	
9	207/39-41	BTTR	11.10	12.10	60	Inspection of SEJ no.6 UP line	
10	207/39-37					Inspection of Pt. No S 16A, South Yard of BTTR yard, Angle 1 in 12, section 60Kg, TWS, FSL	
11	208.25					<ul style="list-style-type: none"> <li>• Inspection of Bitragunta station.</li> <li>• Inspection of Gang No.5 of SSE/P.way/BTTR</li> <li>• Inauguration of Crew Booking Lobby.</li> <li>• Inauguration of New Freight Examination Facility and New C&amp;W Office.</li> <li>• Inspection of Running Room.</li> <li>• Progress of BTTR Longer Loop.</li> </ul>	
12	224/0-254/0	KVZ-SKM				Speed test 120KMPH for Km 30kms.	

13	256/20-22	UPD-SKM				Inspection of Bridge No.517B (RUB), Span 1x5.00m	Subjected to movement of trains. P/2390 (MS-GAYA@13.20 ,P/02249 SBC-NTSK @13.55)
14	269/22-270/6	SKM-TNR	12.50	13:10	20	Inspection of Major Bridge No.533DN, Span 33x12.19 m	
	272.07	TNR Station	13:15	14:20	65	Lunch at Respective Saloons	P/2390 (MS-GAYA@13.20 ,P/02249 SBC-NTSK @13.55),02870 MAS-VSKP @14.05), 02656 CEN-ADI @14.12)
15	277/18-20	TNR-SDM				Inspection of Derailment oil tankers (BTPN) site at km 277/17-19 Up dated 25.06.2020.	Subjected to movement of train 02870 MAS-VSKP @14.05), 02656 CEN-ADI @14.12)
16	316/6-18	UGD-CJM	15.00	15:30	30	Inspection of Br.No.608(DN) , Romperu river, Span 5x30.48m+1x45.72m, Girder	
17	316/18-20	UGD-CJM				Inspection of SEJ No. 7A DN line	
18	316/20-42	UGD-CJM				Inspection of C.No.17 Degree :1.50	
19	316/6-18	UGD-CJM				Inspection of Gang No.3 of SSE/P.Way/CLX	
20	340/13-9	CLX	15.55	16.15	20	Inspection of PT No.N19B, 1 in 12 60kg PSC fan shaped	P/-02878 ERS-HWH @ 15.50
21	359/30-38	BPP-APL	16:35	16.45	10	Diversion of track through New Bridge No.617	
22	371/1-3	APL - NDO	17.00	17.15	15	Inspection of formation treatment work using stone column method by RVNL.	
23	389/34-390/2	TSR-TEL	17:40	17:50	10	Inspection of LC no.281, Non Interlock, C class, TVUs 20,790.	
24	397.25	TEL	18.00	18:30	30	Inspection of Health Unit Inspection of staff quarter and colony, Inspection of Electrical (General Service) Sub Station.	
25		BZA	19.00	--			
<b>Total</b>					<b>340</b>		